

Plate 1: General view of the access to the east of the site.





EARTH SCIENCE PARTNERSHIP33 Cardiff Road, Taffs Well, Cardiff CF15 7RB
Tel: 029 2081 3385 enquiries@earthsciencepartnership.com



Plate 3: General view of TP1.



Plate 4: General view of TP1, weathered bedrock at the base of the pit.



EARTH SCIENCE PARTNERSHIP

33 Cardiff Road, Taffs Well, Cardiff CF15 7RB
Tel: 029 2081 3385 enquiries@earthsciencepartnership.com



Plate 5: General view of TP3, showing both sides of A and B.



Plate 6: View of IP3B, loose cobbles spalling.



EARTH SCIENCE PARTNERSHIP

33 Cardiff Road, Taffs Well, Cardiff CF15 7RB
Tel: 029 2081 3385 enquiries@earthsciencepartnership.com



Plate 7: General view of TP4.



Plate 8: General view of TP5, and arisings of weathered rock in excavator bucket.



EARTH SCIENCE PARTNERSHIP33 Cardiff Road, Taffs Well, Cardiff CF15 7RB
Tel: 029 2081 3385 enquiries@earthsciencepartnership.com



Plate 9: General view of TP6, loose Made Ground.



Plate 10: General view of TP7 with sallow bedrock.



EARTH SCIENCE PARTNERSHIP

33 Cardiff Road, Taffs Well, Cardiff CF15 7RB
Tel: 029 2081 3385 enquiries@earthsciencepartnership.com